### Public Document Pack





# Residents' and Environmental Services Policy Overview Committee

Date: WEDNESDAY, 29 APRIL 2015

Time: 5.30 PM

Venue: COMMITTEE ROOMS 3 & 3A - CIVIC CENTRE, HIGH STREET, UXBRIDGE, MIDDLESEX UB8 1UW

MeetingMembers of the Public andDetails:Press are welcome to attendthis meeting

This agenda and associated reports can be made available in other languages, in braille, large print or on audio tape. Please contact us for further information.

#### **Councillors on the Committee**

Michael White (Chairman) David Yarrow (Vice-Chairman) Lynne Allen Teji Barnes Mohinder Birah Peter Davis Patricia Jackson Kuldeep Lakhmana (Labour Lead) Carol Melvin

Published: Tuesday, 21 April 2015

Contact: Ainsley Gilbert Tel: 01895 250692 Fax: 01895 277373 Email: <u>agilbert@hillingdon.gov.uk</u>

This Agenda is available online at: http://modgov.hillingdon.gov.uk/ieListMeetings.aspx?CId=114&Year=0

Putting our residents first

Lloyd White Head of Democratic Services London Borough of Hillingdon, 3E/05, Civic Centre, High Street, Uxbridge, UB8 1UW www.hillingdon.gov.uk

# Useful information for residents and visitors

#### **Travel and parking**

Bus routes 427, U1, U3, U4 and U7 all stop at the Civic Centre. Uxbridge underground station, with the Piccadilly and Metropolitan lines, is a short walk away. Limited parking is available at the Civic Centre. For details on availability and how to book a parking space, please contact Democratic Services

Please enter from the Council's main reception where you will be directed to the Committee Room.

#### Accessibility

An Induction Loop System is available for use in the various meeting rooms. Please contact us for further information.

#### **Reporting and filming of meetings**

Residents and the media are welcomed to report the proceedings of the public parts of this meeting. Any individual or organisation wishing to film proceedings will be permitted, subject to 48 hours advance notice and compliance with the Council's protocol on such matters. The Officer Contact shown on the front of this agenda should be contacted first for further information.

#### **Emergency procedures**

If there is a FIRE, you will hear a continuous alarm. Please follow the signs to the nearest FIRE EXIT and assemble on the Civic Centre forecourt. Lifts must not be used unless instructed by a Fire Marshal or Security Officer.

In the event of a SECURITY INCIDENT, follow instructions issued via the tannoy, a Fire Marshal or a Security Officer. Those unable to evacuate using the stairs, should make their way to the signed refuge locations.



# **Terms of Reference**

A central role of a Policy Overview Committees is to undertake in-depth policy reviews on specific issues. Reviews provide the opportunity to hear from members of the public and expert witnesses, including people from a wide range of external organisations. Reviews usually make recommendations to the Cabinet on how the Council could improve its work. They therefore perform an important role in opening up the policy-making process to a wider audience, including people who would not normally have the opportunity to participate.

This Committee undertakes the policy overview role in relation to the following matters:

- Highways, traffic, parking & street environment
- Local transport, including rail, cycling & London Underground
- Footpaths and Bridleways
- Road safety and education
- Planning & Building Control
- Libraries
- The Borough's heritage and history
- Sport & Leisure services
- Waste management & recycling
- Green spaces, allotments, woodlands, conservation and sustainable development
- Consumer Protection, Trading Standards & Licensing
- Registrars & Bereavement Services
- Local watercourses, drainage and flooding
- Environmental Health, Air & Noise Quality
- Local impacts of Heathrow expansion
- Local impacts of High Speed Rail

# Agenda

#### **Chairman's Announcements**

1	Apologies for Absence	
2	Declaration of Interest in matters coming before this meeting	
3	To confirm that all items marked Part 1 will be considered in Public and that any items marked Part 2 will be considered in Private	
4	To agree the Minutes of the previous meeting	1 - 4
5	Update on the Council's and other bodies' responses to flooding in the Borough	5 - 30
6	The Treatment of War Memorials	31 - 32
7	Forward Plan	33 - 36
8	Work Programme for the 2015/16 Municipal Year	37 - 38

**Minutes** 

#### RESIDENTS' AND ENVIRONMENTAL SERVICES POLICY OVERVIEW COMMITTEE



#### 25 March 2015

#### Meeting held at Committee Room 5 - Civic Centre, High Street, Uxbridge UB8 1UW

	<b>Committee Members Present</b> : Councillors Michael White (Chairman), David Yarrow (Vice-Chairman), Lynne Allen, Teji Barnes, Mohinder Birah, Peter Davis, Patricia Jackson, Kuldeep Lakhmana (Labour Lead) and Carol Melvin.
	<b>LBH Officers Present</b> : Bill Hickson, Colin Russell (Waste Division Manager) and Ed Shaylor (Residents Services - ASB & Investigations Team), Ainsley Gilbert (Democratic Services).
48.	APOLOGIES FOR ABSENCE (Agenda Item 1)
	There were no apologies for absence.
49.	DECLARATION OF INTEREST IN MATTERS COMING BEFORE THIS MEETING (Agenda Item 2)
	There were no declarations of interest.
50.	TO CONFIRM THAT ALL ITEMS MARKED PART 1 WILL BE CONSIDERED IN PUBLIC AND THAT ANY ITEMS MARKED PART 2 WILL BE CONSIDERED IN PRIVATE (Agenda Item 3)
	It was confirmed that all matters would be considered in part 1.
51.	<b>TO AGREE THE MINUTES OF THE MEETING HELD ON 25 FEBRUARY 2015</b> (Agenda Item 4)
	<b>RESOLVED:</b> That subject to a typographical correction in minute item 44, the minutes be agreed as an accurate reflection of the meeting.
	Councillor Allen asked whether the Footpaths and Bridleways budget to which Paul Richards had referred (minute item 43, paragraph 3) was the budget spent to date, or the annual budget. The clerk agreed to ask Mr Richards for clarification.
	Councillor Allen asked whether any progress had been made on taking the Street Champions report to Cabinet. The Chair explained that it was taking some time for the issue regarding data to be resolved, and so the report remained on hold.

52.	THE CLEANING AND MAINTENANCE SCHEDULE FOR HILLINGDON'S FOOTPATHS AND BRIDLEWAYS - DRAFT FINAL REPORT (Agenda Item 5)
	Members discussed the report. They felt that Hillingdon Equestrian Advisory Committee ought to be given more support to hold meetings.
	<b>RESOLVED:</b> That subject to the addition of ' <i>and that officers will provide meeting rooms to HEAC as and when they consider it to be appropriate.</i> ' to the end of recommendation 4, the report be agreed, and recommended to Cabinet.
53.	UPDATE ON FLY TIPPING IN THE BOROUGH AND THE USE OF CCTV AS A METHOD OF SURVEILLANCE (Agenda Item 6)
	Colin Russell explained that low level fly tipping had increased, whilst the number of large scale incidents had declined. He explained that catching fly tippers had become more difficult as when officers searched for evidence of the origin of rubbish, they often found that the refuse did not contain any personal information. Mr Russell clarified that the figure of 4,500 fly-tips quoted in the report only related to reported fly tips on highways land. There were many more single item or small fly tips which were not reported, or which were on private property.
	In response to questions from Councillors, it was clarified that the Borough was not responsible for collecting fly-tipped waste from private land, but would occasionally do so where it was causing a major obstruction or serious harm. There was a charge for larger cases of this type. Ed Shaylor explained that there was a large amount of legislation relating to the responsibility for clearing fly-tips, and that residents were often unhappy when they found that they were responsible for clearing private alleyways and the like. Officers felt however that it would not be prudent to clear waste tipped on private land too frequently, as it might encourage more tipping. Presently residents were guided through how to deal with any such incidents themselves.
	Councillors asked how the £250,000 cost had been calculated. Officers explained that this cost was mostly the cost of disposing of waste, at £116 per ton. There were also two vans and crews dedicated to cleaning fly tips, and the costs of this was included in the figure.
	Councillors noted the problems that frequently changing tenants could cause. Officers agreed that there was a large amount of waste associated with tenancy changes. A particular problem was mattresses, 10-15 of which were collected from across the borough every day.
	<ul> <li>Members discussed possible ways of improving the service, including:</li> <li>Using household waste collection crews to report fly tips, although they noted the practical difficulties of doing this;</li> <li>Adding publicity regarding the Borough's Household Special Collection Service to literature regarding fly tipping, as appropriate;</li> <li>Installing notices at garden centres regarding the recycling of plastic flowerpots.</li> </ul>
	Councillor Allen thanked Colin Russell for the work he had done in Townfield Ward, which had significantly reduced the impact of fly-tipping and had made residents feel more responsible for their neighbourhood.

54.	UPDATE ON ROADSIDE MEMORIALS POLICY (Agenda Item 7)
	The Chairman said that he felt that it would be prudent to review the operation of the Roadside Memorials Policy after a year of operation. He was concerned however that there was no requirement that officers contact families soon after the erection of any memorial to inform them of the restrictions of the policy.
	Members were disappointed that they had not reviewed the policy prior to its approval by the Cabinet member. They were also concerned that a draft of a letter and the Funeral Procedures Booklet had not been provided to them. Ed Shaylor explained that grieving families were generally contacted in person, and as such no standard letter had been drafted. The Funeral Procedures Booklet was being re-drafted, and as such had not been provided. The section of the brochure regarding roadside memorials had however been included in the report to the committee. The Chairman asked that the booklet be passed to the committee for comment, before it was printed. Members felt that it was important that residents were made aware of the policy, and asked that the text to be included in the Funeral Procedures booklet directly reference the 13 month limit on roadside memorials.
55.	FORWARD PLAN (Agenda Item 8)
	The report was noted.
56.	WORK PROGRAMME (Agenda Item 9)
	Councillors suggested the following issues as possible future review topics: - Legal Highs - Street Cleaning
	Members also asked, with reference to a previous suggestion, that a briefing paper on the misuse and mistreatment of War Memorials be brought to the next meeting.
	The meeting, which commenced at 5.30 pm, closed at 6.40 pm.

These are the minutes of the above meeting. For more information on any of the resolutions please contact Ainsley Gilbert on 01895 250692. Circulation of these minutes is to Councillors, Officers, the Press and Members of the Public.

# Agenda Item 5

# Update on the Council's and other bodies' responses to flooding in the Borough

Contact officer: Vicky Boorman Telephone: 01895 277920 Email: <u>vboorman@hillingdon.gov.uk</u>

#### **REASON FOR ITEM**

At its meeting on 20 November 2014 the committee requested that regular updates on the Council's response to flooding be added to its work programme.

#### INFORMATION

Since the November meeting there have been no major flood events in the Borough. Another Flood Investigation Report, on the significant flooding which happened on 28 July 2014, has been published on the Hillingdon website. Information for the report was gathered directly from residents as well as from the Contact Centre. The report is appended to this paper.

The map setting out ownership and responsibilities for larger drainage infrastructure such as ditches and trash screens remains a work in progress.

The Hillingdon Flood Risk Management Strategy, which members were informed about at the last meeting, has now been drafted and is being reviewed by officers, before wider consultation takes place.

#### RECCOMENDATION

1. That the committee note the report.

# **FLOOD INVESTIGATION REPORT**

### July 28th 2014

The report is produced to fulfil Lead Local Flood Authority requirements to investigate significant flooding under Section 19 of the Flood and Water Management Act 2010, which states:

"On becoming aware of a flood in its area, a lead local flood authority must, to the extent that it considers it necessary or appropriate, investigate -

Which risk management authorities have relevant flood risk management functions, and

Whether each of those risk management authorities has exercised, or is proposing to exercise, those functions in response to flood.

Where an authority carries out an investigation under subsection 1) it must -

- (a) Publish the results of its investigations; and
- (b) Notify any relevant risk management authorities".



Page 7

#### **Contents Page**

1.	Overview of Flood Risk in Hillingdon			
2.	Summary of 28 <sup>th</sup> July Event	3		
3.	Summary of Impact	3		
4.	Summary of Response	6		
а	A40 adjacent to Hillingdon Underground Station	7		
b	Bedford Road, Clyfford Road and West End Road	8		
С	Station Approach, Ruislip HA4 6TP	. 10		
d	Derwent Avenue, Ickenham UB10 8HJ	. 11		
е	High Road and Austins Lane, Ickenham UB10 8RH	. 12		
f	Glebe Avenue, Ickenham UB10 8PQ	. 13		
g	The Avenue, Ickenham UB10 8NR	. 15		
h	Rockingham Parade and The Lynch, Uxbridge UB82TQ	. 16		
i	Regents Avenue and Windsor Avenue Uxbridge UB10 9AT	. 17		
j	Cowley Road, Uxbridge UB8 2LT	. 18		
k	Wood End Green Road UB3 2SF	. 19		
Ι	Blossom Way, West Drayton UB7 9HG	. 20		
n	n Generic queries regarding flooding	.21		
5.	Conclusion	.22		
6.	Key links and sources	.24		

#### 1. Overview of Flood Risk in Hillingdon

Hillingdon Council is susceptible to a number of different sources of flooding. Within its boundaries lie the River Colne and River Crane catchments, the River Pinn and Yeading brooks and numerous ordinary watercourses.

The Council has also identified large areas as being at risk from surface water according to maps produced by the Environment Agency 'Risk of Flooding from Surface Water<sup>1</sup>' (which can be found on their website).

Flooding could affect over 5212 people in the borough. Further information on these risks can be found in Hillingdon's Strategic Flood Risk Assessment and Surface Water Management Plan available on the Council's Website<sup>2</sup>.

#### 2. Summary of 28<sup>th</sup> July Event

#### Warning

A Flood Guidance Statement was issued by the Met Office on Sunday 27th for the 28th July, "The surface water flood risk was considered low across the south-east of England as a result of a low likelihood of significant impacts from isolated heavy showers or thunderstorms".

#### Causes of flooding

Torrential rain, with lightning and thunder, began at about 7.00am in the Uxbridge area and quickly caused large areas of standing water. In Ruislip it started about 09.00am BST and lasted for at least 45 minutes

The Met Office recorded more than 42.6mm of rainfall in Northolt at 8.00am. More than half the average total rain for England in July fell in an hour.

A flood alert was issued for the 'Lower River Colne and Fray's River' at approximately 10.45 am by the Environment Agency in response to the rain that had fallen.

#### 3. Summary of Impact

A large number of roads were temporarily flooded, some of which were impassable as a result, including key infrastructure such as the A40. London Underground train stations and lines were also closed off in the Hillingdon area.

In Hillingdon approximately 29 properties flooded internally. Some of these residents are still affected and some have not been able to return to their homes and are in temporary accommodation.

At one stage six cars were stuck in floodwater in Uxbridge, west London, according to the AA's Special Operations Response Team. A number of people were rescued after being stranded in flood water.

A number of sources have been used to collate this information. As only a limited number have been direct reports to the Council, not all have been able to be verified. There may be other areas that the Council are not yet aware of.

<sup>&</sup>lt;sup>1</sup> <u>http://watermaps.environment-</u>

agency.gov.uk/wiyby/wiyby.aspx?topic=ufmfsw#x=357683&y=355134&scale=2 <sup>2</sup> http://www.hillingdon.gov.uk/26402

The flooding reports were mainly from the Ruislip and Northolt Area, although there were some localised issues in Uxbridge and West Drayton. The majority of issues appear to have been due to heavy rain overwhelming surface water sewers.

Key impacted sites are explored in more detail in the next section.



Map of Key areas affected on the 28<sup>th</sup> July.

#### London Underground infrastructure affected:

- West Ruislip Station flooding nearby
- South Ruislip Station flooded and closed.
- Ruislip Manor Station on Victoria Road, subway flooded
- Ruislip Station and
- Eastcote Station on Field End Road closed for a period while the floods were dealt with by engineers.

The Metropolitan and Piccadilly lines were closed between Ruislip and Rayners Lane after tracks disappeared under flood water.

#### Roads affected by area

Ward	Road Name		
Eastcote	High Road,		
Harefield	Hill End Road.		
	Cowley Road		
	The Lynch		
	Regents Avenue		
Uxbridge	Granville Road/		
	Windsor Avenue -		
	Photos		
	Turnpike Lane		
	Ruislip Gardens		
	Victoria Road		
	Bedford Road		
Desiglia	Clyfford Road		
Ruislip	Lea Crescent		
	Station Approach		
	Westfield Way Cornwall Road		
	Pembroke Road		
	Swakeleys Road		
	Derwent Avenue		
	Thornhill Road		
	St Georges Road		
	Breakspear Road South		
	Parkfield Road		
Ickenham	High Road		
	Austins Road,		
	Glebe Avenue		
	Sussex Road		
	Milverton Drive		
	Edinburgh Road		
	Blossom Road		
West Drayton	Hatch Lane		
	Money Lane		
Harmondsworth	Holloway Lane		
Harlington	High Street		
	Wood End Green Road		
Hayes	Lansbury Drive		
	Fairholme Crescent		

Other - Battle of Britain Bunker

#### 4. Summary of Response

#### Lead Local Flood Authority response

Hillingdon has a clear process in place through the Civil Protection Service in which adverse weather warnings are distributed within the Council so that officers in different services can take the appropriate action. In an emergency, Hillingdon has on standby a number of officers, ready to respond.

The Council Highways service attended a number of sites over this period during the morning as requested by residents. They delivered sandbags to residents, as well as visiting a number of structures across the borough to remove debris and thus reduce the likelihood of blockages.

#### Other Risk Management Authorities (RMA) responses

Thames Water responded to a number of queries from residents, and attended a number of sites at the time of the event. TFL also responded to the event on the A40 which required tankers to pump out water to allow the road to reopen.

#### Investigation

Although this is considered unprecedented weather, the Council wants to ensure that flood events are investigated to ensure that any contributing factors are being managed appropriately by the Council and the other risk management bodies.

The impact was significant to a large number of residents whose houses were flooded internally and a number have not been able to return home.

Investigation is recommended by the Surface Water Management Plan Appendix C Actions. In addition, under Section 19 of the Flood and Water Management Act 2010 Hillingdon as a Lead Local Flood Authority (LLFA) consider investigation appropriate.

Evidence has been collected from the numerous calls, emails and letters that the Council has received over this period, as well as meetings with residents, and information from local media reports. Requests have also been made to other flood risk management partners for information.

Area affected	a A40 adjacent to Hillingdon Underground Station		
Date of flooding	28/07/2014		
<b>Grid Reference</b> 507664 185051		0785SE	
Land ownership	TFL responsible		
Map of Area		Photo	
Location of flooding ma Critical Drainage Area i		Tailback on A40 due to closure, Photo of water posted by Uxbridge South police team to twitter	
Duration of flooding	Approximately 12 hours		
Source of flooding	urce of flooding Surface Water		
Cause/Pathway	Cause/Pathway Heavy rain in a very short period resulted in the overwhelming of surface water drainage arrangements and water built up in low poor on the A40		
Impact of flooding	A40 closed, diversi	ons and tailbacks across Hillingdon	
Evidence	<b>.</b> .	a variety of sources. The area is also defined as rea, within the SWMP.	
History of flooding None			
SummaryIdentified as an area of risk within the Hillingdon Surface Water Management Plan (2011) and published on the Hillingdon websit A copy was provided to Transport for London 22 <sup>nd</sup> Jan 2013.		(2011) and published on the Hillingdon website.	
Action by TFL	Investigate and determine appropriate actions and share discuss with the Council as the Lead local Flood Authority		
Action by the Council	Further investigation has been undertaken by the Council working with the GLA and Drain London but no information on the drainage infrastructure in the area has been provided by TFL despite repeated information requests. The investigation undertaken by TFL has been requested by the Council on a number of occasions since the event but not yet provided.		

Area affected	b Bedford Road, Clyfford	Road and West End Road HA4 6NA	
Date of flooding	28/07/2014		
Grid Reference	509876 185800		
Land ownership	LBH adopted roads and re	sidents	
Map of Area	Photo		
Blue indicates fluvial flo water taken from EA FI	Location of flooding marked as a red star. Blue indicates fluvial flooding and purple surface water taken from EA Flood Maps Red dots indicate Thames Water Surface water sewer outfalls		
Duration of flooding	Approximately 3 hours		

Duration of flooding Approximately 3 hours		
Source of flooding	Surface Water	
Cause/Pathway	Overwhelming of surface water sewer, water building up in the low points in the roads and spilling out and over the footpaths and into front gardens. Water levels also built up rear of some properties.	
Impact of flooding	Flooding across access roads and in approximately 23 houses	
<b>Evidence</b> Photos and anecdotal reports from the Get West London. Th location is identified on the Environment Agency Flood Map a area at risk from surface water and fluvial flooding. The area i within a Critical Drainage Area.		
History of flooding	None, although on West End Road there have been previous reports of flooding although more details are not known	
Summary	Heavy rain within a very short period of time overwhelmed the local drains. The London Fire Brigade (LFB) attended the scene on the 28 <sup>th</sup> July to assist residents. Sandbags provided by LFB to 20 -50 properties affected, some internally.	
Action by the Residents	The Council recommends that where appropriate residents identify what they can do to protect themselves. Products that may help such as air brick covers, with information about them and links to where they can be found on the internet are on the 'flooding' page on Hillingdon website.	

Water	Thames Water has said they will monitor the situation and respond to future reports. The Council have requested that Thames Water investigate the whole length of surface water sewer to the point of discharge into a river so that it can be confirmed that the system functions appropriately.
Action by Thames	Thames Water are responsible for the surface water sewer that gullies drain into. Thames Water visited the site in August on request of residents and undertook a CCTV survey of the surface water sewer. However they were prevented from completing this because the line was blocked. Further work was commissioned by Thames Water for their contractors to undertake a line clean of the surface water sewer. Tree roots which had blocked the line were cut back.
	Council officers have also checked the Thames Water surface water outfalls and found water flow from them to be impeded by silt and vegetation and have reported it to Thames Water to investigate and take action.
Council	<ul><li>washed into gullies, blocking them even if they had been previously clear prior to the flood event.</li><li>The Council has invested in a new system to review the prioritisation of the gullies so that gully clearing could be more frequently to high priority sites less frequent in less critical areas.</li></ul>
Action by the	jetted with water to ensure the connections into the sewers are clear. It should be noted that, in heavy rain, leaves and other debris is
	The Council are responsible for the gullies in an adopted Highway. The gullies are cleaned on a yearly basis by the Council, and are in this area scheduled to be cleaned in approximately August every year. The gullies were cleaned on 4th August 2014. A number of gullies were covered by parked cars and the Highways service returned at a later date to clear these. Where gullies are blocked the debris is removed and the gullies
	Every resident should report issues to Thames Water to ensure that the reports they receive reflect the severity of the situation, and the numbers truly affected.
	In addition there is concern by residents that the access road to the rear of the properties may be contributing to flooding. These roads are privately owned and the Council holds no information on their current drainage arrangements. Residents need to work together to ensure that the drainage arrangements are maintained by the owner.
	Additionally increasing the permeable areas will help reduce the water flowing towards the sewers. Any new front gardens which are paved should comply with GDPO requirements to ensure they are either permeable or drain to a permeable area within the garden.

Area affected	c Station Approach, Ruislip HA4 6TP		
Date of flooding	28/07/2014		
Grid Reference	511149 185418		
Land ownership LBH Adopted Hig		way	
Map of Area		Photo	
Location of flooding star	marked as a red	Taken by Alan Palmer           http://www.getwestlondon.co.uk/news/local-news/two-           women-rescued-car-south-7518302	
Station (Luc) (Luc			
Duration of flooding Approximate		3 hours	
Source of flooding	Surface Water	Surface Water	
Cause/Pathway	Overwhelming	Overwhelming of surface water sewer	
Impact of flooding			
Evidence	location is iden	Reports from residents to the Council and news papers. The location is identified on the Environment Agency Flood Map as an area at risk from surface water.	
History of flooding         30/11/2009, 11/06/2012, 18/07/2012, 27/10/2013, 5/11/2013, 7/02/2014, 14/05/2014			
Summary	2 ladies rescue	2 ladies rescued by LFB on the 28 <sup>th</sup> July after becoming stranded.	
Action by the Coun	on the 28 <sup>th</sup> July approximately team were able of occasions and surface water so Water on nume	Council Highways services were called by residents and attended on the 28 <sup>th</sup> July. They used a tanker to remove water until approximately 4pm when Thames Water arrived. The Council team were able to point out the locations of the blockage. Gullies have been checked previously by the Council on a number of occasions and found to be clear. However a blockage in the surface water sewer was identified. It was reported to Thames Water on numerous occasions by the Council over the last few years, following resident's reports of other issues.	
Action by Thames Water	Thames Water roots blocking been undertake the dig out of a	Issue reported by the Council to Thames Water in October 2013. Thames Water have attended site on a number of occasions. Tree roots blocking the pipe were found. Works to clear this had still not been undertaken in July 2014. Road closure is required to enable the dig out of and replacement of the pipe work and replace it, as the blockage cannot be moved.	

Area affected	d Derwent Avenue, Ickenham UB10 8HJ	
Date of flooding 28/07		/2014
Grid Reference 5072		08 186437
Land ownership	LBH a	adopted Highway
Map of Area		
Location of flooding marked as red star	а	none
Duration of flooding Approx 24 hours.		ox 24 hours.
Source of flooding Surface		ce Water
Cause/Pathway Overv		vhelming of surface water sewer
Impact of flooding	Road flooded, and one home flooded internally	
Evidence	Anecdotal evidence from residents. The location is identified on Environment Agency Flood Map as an area where water at risk from surface water.	
History of flooding	5 times in 2006, twice previously in 2014	
Summary	Surface water flooding from overwhelming of the drains. The Thames Water network drains into the Ickenham stream at the end of Glebe Avenue.	
Action by the Council	Gullies that the Council are responsible for are checked on a yearly basis. They have also been checked again following this incident and it was confirmed they are running clear.	
Action by Resident	Resident advice to contact Thames Water to confirm there was no capacity issue	

Area affected	e High Road and Austins Lane, Ickenham UB10 8RH	
Date of flooding	28/07/2014	
Grid Reference	508099 186245	
Land ownership	LBH adopted Highway and residents managed by private management company	
Map of Area		
Location of flooding ma as a red star	rked Photo from Get West London	
With         School           With         School		
Duration of flooding	Approx 24 hours.	
Source of flooding	Surface Water and Ordinary watercourse (unconfirmed)	
Cause/Pathway	Unconfirmed presumed to be water not draining away into the Ickenham stream	
Impact of flooding	Road flooded, almost flooding houses on Church Place and Tweedale Grove	
Evidence	Anecdotal evidence from residents. The location is identified on the Environment Agency Flood Map as an area at risk from surface water.	
History of flooding	none	
Summary	Residents tried to report issue to the Council but could not get through, to anyone after a couple of minutes.	
Action by the Council	To investigate maintenance regime of landowner of ordinary watercourse	

Area affected	Glebe Avenue, Ickenham UB10 8PQ	
Date of flooding	28/07/2014	
Grid Reference	508480 185679	
Land ownership	Adopted Highway	
Map of Area		
Location of flooding	marked as a red star	
Glebe Primary School		
Duration of flooding	Approximately 3 hours	
Source of flooding	Surface Water	
Cause/Pathway	Highway	
Impact of flooding	Flood water flowed across road and into 4 households.	
Evidence	Photos and correspondence from residents	
History of flooding	1975, 1976 unverified, 1977 flood water entered homes, 1978, 1993, 2006 foul water entered gardens and garages, 2014 flood water entered homes. Identified on the Environment Agency Flood Map for Surface Water as a low lying area.	
Summary	Surface water flooding from the overwhelming of the drains, which also caused issues with foul network. The Thames Water network drains into the Ickenham stream at the end of Glebe Avenue.	
	Council officers have raised the following issues with other bodies:	
	The need for ongoing maintenance by Thames Water on the surface water sewer main	
Action by the Coun		
	<ul> <li>The Council have also requested the Environment Agency review their river level monitoring and flood warnings within Hillingdon to see if areas currently not covered can be provided with a warning.</li> </ul>	

	The Council has undertaken the following:
	Gullies are cleared on an annual basis.
	• The clearance of the Ickenham stream by contractors has been prioritised to ensure it is flowing properly. Work is scheduled for November/ December 2014.
	Ickenham Residents Association are collecting information on future flood events and mapping them and providing that to the Council.
Action by residents	The Council recommend that residents draw up a Flood Plan. Further information about this can be found on the Hillingdon website. Also on products to protect houses from flooding through airbricks
Action by Thames Water	Thames Water have attended site since the event on a number of occasions. In November 14 is Glebe Avenue was partially cleared However manhole covers were jammed, so work is proposed to free them.
Action by the Environment Agency	The Environment Agency is funded by DEFRA to undertake maintenance on main rivers. This is focused on high priority areas, and the Environment Agency has advised that, because the Ickenham stream is not at risk from main river flooding, it is not proposed for maintenance by the Environment Agency. No flood warning is issued for the Ickenham Stream.

Area affected	g The Avenue, Ickenham UB10 8NR		
Date of flooding	ng 28/07/2014		
<b>Grid Reference</b> 507473 186082			
Land ownership	Residents.		
Map of Area		Photo	
Location of flooding marked as	a red star	28 <sup>th</sup> July 2014 Taken by resident	
Duration of flooding	Approximately 3 h	iours	
Source of flooding	Foul Water		
Cause/Pathway	Unconfirmed		
Impact of flooding	A number of garages and the highway		
<b>Evidence</b> Anecdotal evidence from the Council and residents.		ce from the Council and residents.	
History of flooding none			
Summary	Reports from resident the River Pinn.	dents regarding the foul sewer flowing into	
Action by Thames Water	Reported to Thames Water by residents Reference 0081/03SGWZ. CCTV survey shows fractures in the pipe which needs to be resolved. Works ongoing.		

Area affected	h Rock	Rockingham Parade and The Lynch, Uxbridge UB82TQ	
Date of flooding	28/07/2	28/07/2014	
Grid Reference	505379 183540		
Land ownership	Adopte	d Highway	
Map of Area		Photo	
Location of flooding as a red star. Blue in fluvial flooding show Flood Zones	dicates	Taken by Steve Terrill GET West London http://www.getwestlondon.co.uk/news/local-news/in-pictures- flooding-hits-hillingdon-7518585	
A 11 Guins			
Duration of floodin		Approximately 3 hours	
Source of flooding	Riv	er Colne	
Cause/Pathway	<b>Cause/Pathway</b> The River Colne water levels rose due to the amount of rain fa and a Flood Alert was issued for the area by the Environment Agency at 10:43am		
Impact of flooding		Flood water flowed across the road and into front gardens. Unverified reports of flooding through airbricks.	
Evidence	Pho	Photos and reports from residents	
History of flooding		None, but identified as being within an area at risk of fluvial flooding on the Environment Agency Flood Map.	
Summary	Riv	River levels were high	
Action by the Coun	cil Co	Continued monitoring of the situation	
Action by the residents	info pro	The Council recommend residents draw up a Flood Plan. Further information can be found on the Hillingdon website. Also on products that can be purchased to protect homes from flooding through airbricks.	

Area affected	i Regents Avenue and Windsor A	Regents Avenue and Windsor Avenue Uxbridge UB10 9AT		
Date of flooding	28/07/2014	/07/2014		
Grid Reference	08193 184513			
Land ownership	Adopted Highway			
Map of Area		Photo		
hatching defines the	narked as a red star, purple critical drainage area, with shaded y to be at risk from surface water	Taken by resident		
Duration of flooding	Approximately 3 hours			
Source of flooding	Surface Water			
Cause/Pathway	Water built up in the road flowing and into some homes.	Water built up in the road flowing over footpaths into front gardens and into some homes.		
Impact of flooding	Flood water flowed across the some cases; this resulted in ho	road and into front gardens and in puses being flooded internally.		
Evidence		Photos and reports from residents. The area is also within a Critical Drainage Area identified by the SWMP		
History of flooding		None, but identified as within an area at risk of surface water flooding on the Environment Agency Flood Map.		
Summary	Flood water built up and flowed	Flood water built up and flowed into houses very quickly		
Action by the Coun	cil To record the event, and refer	To record the event, and refer to Thames Water		
Action by the residents	information can be found on the	The Council recommend residents draw up a Flood Plan. Further information can be found on the Hillingdon website. Also on products that can be purchased to protect homes from flooding through airbricks.		

Area affected	j Cowley I	Cowley Road, Uxbridge UB8 2LT	
Date of flooding	28/07/2014		
Grid Reference	505376 183544		
Land ownership	Adopted H	lighway	
Map of Area		Photo	
Location of flooding n a red star	narked as	Taken by London Borough of Hillingdon Officer	
Duration of flooding	ation of flooding Approximately 3 hours		
Source of flooding	Surfac	ce Water	
Cause/Pathway	Overw	helming of surface water sewer by heavy rain.	
Impact of flooding		ey Road closed to buses, with tailbacks and diversions	
		ey Road Uxbridge <u>28th July 2014 -</u> YouTube	
Evidence wv		www.youtube.com/watch?v=DHOWfN27zY0 1 day ago - Uploaded by Nigel Clark Uxbridge Cowley Road flood rain	
History of flooding		None, but identified as being within an area at risk of surface water flooding on the Environment Agency Flood Map.	
Summary	Enviro Tham river.	Lower River Colne and Fray's River. Flood Alert issued by the Environment Agency. The River Colne rose above the level of Thames Water pipes discharging water from the road into the river. This meant that water could not drain away quickly, so that it puilt up in the road until the water level in the river fell again.	
Action by the Counc	il Gullie	Gullies checked to ensure they are clear.	

Area affected	k Wood End Green Ro	Wood End Green Road UB3 2SF	
Date of flooding	28/07/2014		
Grid Reference	508946 181496		
Land ownership	Adopted Highway		
Map of Area		Photo	
Location of flooding	marked as a red star	none	
Participante and a second seco			
Duration of flooding		Approximately 3 hours	
Source of flooding	Surface Water	Surface Water	
Cause/Pathway	Water built up in the	e road flowing over footpaths into front gardens	
Impact of flooding	Flooding of the road	Flooding of the road	
Evidence	Reports from reside	ents	
History of flooding	19/08/2014 28/07/2	Consistently reoccurring issue 23/11/2014, 04/11/2014, 19/08/2014 28/07/2014. Identified as an area at risk of surface water flooding on the Environment Agency Flood Map.	
Summary	Flood water built up	o very quickly	
Action by the Coun	cil 8 <sup>th</sup> October 2014. To continue raising residents with inform	To continue yearly clearance of gullies. Gullies last checked on the 8 <sup>th</sup> October 2014. To continue raising the issue with Thames Water. To provide residents with information on how to dispose of fats and grease - This can be found on the Hillingdon website.	
Action by Thames WaterThames Water have attended site on a number of oc clear both the foul and surface water sewer. Thames Water to send out literature on the proper di and grease as this had blocked the foul sewer.		and surface water sewer. end out literature on the proper disposal of fats	
Action by the residents	e To dispose of fats and grease appropriately. The Council recommend residents draw up a Flood Plan. Further information can be found on the Hillingdon website. Also on products that can be purchased to protect homes from flooding through airbricks. To continue to report all issues to Thames Water.		

Page 25

Area affected	I Blossom Way, West Drayton UB7 9HG	
Date of flooding	28/07/2014	
Grid Reference	507162 178683	
Land ownership	LBH Adopted Roa	ıd
Map of Area		Photo
Location of flooding ma	rked as a red star	Photo taken by resident and sent to the Council
Duration of flooding	Approximately 3 hours	
Source of flooding	Surface Water	
Cause/Pathway	Highway	
Impact of flooding	Road flooded for a	a number of hours
Evidence	Photos and corres	spondence with residents
History of flooding	Flooding reported by residents in Jan 2014. The area is also identified within an area at risk of surface water flooding on the Environment Agency Flood Map for Surface Water.	
Summary	Water ponding on the road was not able to drain away into the soakaways as they were full. A recurring issue.	
Action by the Council	There are no Thames Water surface water sewers in this road. All the drainage currently goes to a soak away in the verge. The Council considered a number of options and has created a new soak away to reduce the extent of flooding. However it should be noted there will be more extreme events which may overwhelm this system.	

	Area affected	m Generic queries regarding flooding	
	Queries	Actions	
1.	Residents providing reports of flooding	Ickenham Residents Association has undertaken to collect information on flood events and provide a Google map of information.	
2 Improved information of responsibilities was required following the investig flooding. This has been made available on the Coun Specifically, residents can search under 'flooding' 'riv		A query in a previous flood investigation. More information on the allocation of responsibilities was required following the investigation into last winter's flooding. This has been made available on the Councils website. Specifically, residents can search under 'flooding' 'rivers' and 'property drainage' for more information on rights and responsibilities.	
3.	Grants Available	Those who suffered flooding in this event are not eligible for the grants from central government made available to those who were affected in last winter's flood events. Other groups are petitioning government to try to get this grant scheme extended.	
4.	4 Responses to road flooding	The Council has a yearly programme of gully clearance. Despite the maintenance undertaken by the Council, problems can occur even when drainage installations are clean and well maintained. Heavy rain can wash leaves and other material into a gully, blocking them. The water flowing into a gully will then flow into a surface water sewer main. Often flooding can occur, even where the gully is clear, because there is a blockage within the surface water sewer. This can often be because of tree roots growing through the sewer. Surface water sewers are the responsibility of the utility companies, and in Hillingdon, this is Thames Water. When very heavy rain falls on the highway in a short period of time it can often exceeds the capacity of the drainage facilities designed to take it away. Thus some water will be visible on a road after very heavy rain. Roads are designed to contain water on the road within the kerbs. Please allow time to see if the water drains away. Water can remain for a while in low spots in the road even when the drainage system is working. If the water remains after a number of hours, report it to the Council to investigate to see if the gully is blocked. If it is the surface water sewer that is blocked, this will need to be reported to the Utility company to investigate,	
		<ul> <li>and cleared. More information on the rights and responsibilities of different parties can be found on the Hillingdon website.</li> <li>If you know it is a gully that is blocked, and have seen a road flood but it has not cleared, please use the following options:</li> <li><u>Report It</u> on the website or call the Hillingdon Contact Centre: 01895 556000</li> </ul>	
		If you know it is a Thames Water Sewer <u>Report it</u> on the Thames Water Website or call them on: 0800 0093964 (choose option 2 and then option2)	

#### 5. Conclusion

The Council has considered investigation findings and puts forward the following actions:

Short Term Actions				
The Council	<ul> <li>As part of the communications plan recommended by a previous flood investigation:</li> <li>To develop a survey, this can be used to obtain more specific information about whom and what is affected. This to be used to develop options to alleviate flooding where possible.</li> <li>Promote the 'roles and responsibilities' information so it is clear to residents what the Council can and can't do to alleviate flooding for residents.</li> <li>Promote this to Street Champions to help get the message out.</li> <li>Ensure that the appropriate information is provided when residents report issues, so the appropriate party can be identified earlier.</li> <li>To continue to work with the Environment Agency in prioritising the area's most at risk of flooding from any source for their maintenance. Environment Agency currently focus the maintenance they are funded to undertake on main rivers on areas affected by fluvial flooding however other areas may be more important as lack of maintenance can affect surface water flooding too.</li> <li>To finalise investigations and provide feedback to residents and contacts directly where issues have been reported.</li> </ul>			
The Environment Agency	<ul> <li>To provide the Council with its flooding review and information on the actions it will be taking.</li> <li>To share more clearly information on management and maintenance and projects to allow the Council and other Riparian owners to develop their own programme of works and maintenance. To recognise that state of main rivers can have an impact of other sources of flooding.</li> </ul>			
Residents	• To take action by producing <u>Community Flood Plans</u> and using the 'resilience' measures tool, (Detailed in the <u>SWMP</u> Options and Actions Plan Part 2 Appendix B).			
Long Term Act				
The Council	<ul> <li>A number of these actions are already established by a previous flood investigation and are already initiated.</li> <li>To review and update the Multi Agency Flood Plan, where necessary to reflect the current flood risks for the borough,</li> <li>To formalise the council's internal flood response plan(s).</li> <li>To review of the ditch management and maintenance programme for the Council. This is already being undertaken by the Flood and Water Management Officer.</li> <li>To review sandbag provision and formulate a clear policy based on cost benefit of reactive response versus the provision of advice by the Council to residents to implement site specific resilience measures.</li> </ul>			

Ongoing actions following every	• To continue working towards delivering the legal requirements of the Flood and Water Management Act 2010 and the Flood Risk Regulations 2009.
Investigation	<ul> <li>To continue implementing the Surface Water Management Plan Part 2 Actions. There are a number of actions to manage flood risk from local sources such as surface water and groundwater which the Council has already set out in the SWMP. Some of these actions are repeated below:</li> </ul>
	<ul> <li>Following this investigation the Council should update the Surface Water Management Plan: Evidence and Action Plans, Appendix A Site Specific Actions and Appendix C Generic Council Actions.</li> </ul>
	Continue to progress site specific projects.
	<ul> <li>To publish the Flood Investigation report and notify other Risk Management Authorities with Actions.</li> </ul>
	<ul> <li>Following investigations, the Council to work with other responsible bodies and identify landowners to ensure they are taking appropriate action to reduce flood risk.</li> </ul>

#### 6. Key links and sources

Organisation	Information	Link
	Flood Map for Surface Water and from Rivers and the Sea	http://watermaps.environment- agency.gov.uk/wiyby/wiyby.aspx?topic=floodmap#x=3 57683&y=355134&scale=2
EA	Flood Plans	https://www.gov.uk/prepare-for-a-flood/make-a-flood- plan
	Making a flood plan Online	http://apps.environment- agency.gov.uk/flood/151256.aspx
	Thames Water To report issues Tel 0845 9200 800 or	http://www.thameswater.co.uk/16266.htm
Thames Water	Appropriate disposal of fats - Thames Water 'Bin it don't block it' Campaign	http://www.thameswater.co.uk/help-and- advice/9137.htm
London Borough of Hillingdon	Flood Risk Portfolio Including: <b>Surface Water</b> Management Plan Part 1 &2	http://www.hillingdon.gov.uk/26402
	Rivers, Ditches and Canals responsibilities	http://www.hillingdon.gov.uk/28579
	Road Drainage responsibilities	http://www.hillingdon.gov.uk/26542
	Information on Property Drainage responsibilities	http://www.hillingdon.gov.uk/12787
National Flood Forum	Information on flood products	http://www.bluepages.org.uk
BBC	Flood Event articles	http://www.bbc.co.uk/news/uk-england-sussex- 28520520 http://www.bbc.co.uk/news/uk-england-london-
Get West London	Flood Event articles	28523652 <u>http://www.getwestlondon.co.uk/news/local-news/in-pictures-flooding-hits-hillingdon-7518585</u> <u>http://www.getwestlondon.co.uk/news/local-news/two-women-rescued-car-south-7518302</u>
		http://www.getwestlondon.co.uk/news/local-news/raf- uxbridge-battle-britain-bunker-7522492

## Agenda Item 6

#### The Treatment of War Memorials

Contact officer: Ainsley Gilbert Telephone: 01895 250692 Email: agilbert@hillingdon.gov.uk

#### **REASON FOR ITEM**

The Committee requested a briefing paper to assess whether there was a problem with the way war memorials are treated in the Borough.

#### **INFORMATION**

- 1. There are 69 War Memorials listed in the Hillingdon Gazetter of War Memorials. However, the majority of these are not in public places. Many are located in schools, or in Churches, and are not generally accessible. There are also a number of graves of UK service personnel in the Borough, notably the 112 ANZAC Hospital graves in Harefield, and some of the Borough's cemeteries also contain war memorials. There are 23 publically accessible War Memorials, of which 11 are located in town or village centres. The focus of this report is on the traditional village or town centre memorials, as these are most likely to suffer from mistreatment, owing to their location.
- 2. There are numerous reports of vandalism across the country, with deliberate acts of vandalism occurring, as well as other examples of mistreatment. In Hillingdon, however, the Council is aware of only a very small number of reports of Anti Social Behaviour (ASB) at or mistreatment of War Memorials.
- 3. Councillor Carol Melvin has reported that people often misuse the Northwood War Memorial owing to its stepped design and proximity local takeaway shops.
- 4. Paul Richards, Head of Green Spaces, Sport and Culture, advises that there have been problems with youths loitering in the vicinity of the war memorial at Harefield, however, this had not led to any damage to the War Memorial. There was also a single political protester at the Polish War Memorial, and whilst this might be considered inappropriate, it is not the kind of mistreatment or ASB which members had previously been concerned about. The ASBIT team were aware only of the instances noted by Paul Richards
- 5. There are undoubtedly other instances of individuals not treating War Memorials in the way which members would hope, however, they have not been reported to the Council. The Council also does a great deal of work supporting remembrance, and highlighting the importance of memorials, for example the recent World War One Book, and the plaques installed at Harefield to honour the two Victoria Cross holders from that village. It is hoped that better knowledge of the purpose of memorials will prevent individuals from acting inappropriately.

#### RECCOMENDATION

6. That the committee note the report, and decide what action, if any, it wishes to take.

## Agenda Item 7

#### FORWARD PLAN

Contact officer: Ainsley Gilbert Telephone: 01895 250692 Email: agilbert@hillingdon.gov.uk

#### **REASON FOR ITEM**

The Committee is required by its terms of reference to consider the Forward Plan and comment as appropriate to the decision maker on key decisions that relate to services within its remit (before they are taken by Cabinet or Cabinet Member).

#### **OPTIONS OPEN TO THE COMMITTEE**

- To comment on items going to the Cabinet or Cabinet Members for decision.
- Or to note the items and decide not to comment.

#### **INFORMATION**

- 1. The Forward Plan for the following months has been published. Those items that are within this Committee's remit are shown on the attached version of the Forward Plan. The Committee may wish to consider and comment on these items.
- 2. Committee Members are requested to send in any questions they have regarding the attached Forward Plan or on any reports going to the next meeting of Cabinet, and to notify any officers that they would like to attend to give advice.

#### SUGGESTED COMMITTEE ACTIVITY

• To consider whether there are comments or suggestions that the Committee wishes to make that will aid Cabinet's decision making.

Private decision?					Private (3)	
ием ітем		NEW	NEW		NEW	NEW
noitatiusnoD noiteab ent no						Various consultees
Officer Contact for further information	lance	FD - Paul Whaymand	RS - Jales Tippell / Vanessa Scott		RS - Adriano Sapelli	RS - James Gleave
kesbousible	nistration FD= Finance	Cllr Ray Puddifoot MBE & Cllr Jonathan Bianco	Cllr Keith Burrows		ClIr Jonathan Bianco	Cllr Keith Burrows
	ices AD = Administration					Date TBC
Ward(s)	cial Care Servi	AII	All		Uxbridge North	AII
ner information	council Departments: RS = Residents Services CYPS = Children and Young People's Services ASCS= Adult Social Care Services Cabinet meeting - 18 June 2015	The Cabinet will receive the details of the budget outturn for 2014/15.	Regular monitoring report with information about spending on section 106 (developer contribution) monies.	Cabinet meeting - 23 July 2015	Darrell Charles Court       Cabinet approval is required for the tender for the roof         - Roof Refurbishment       refurbishment and photovoltaic panel installation works late         & Solar Panels       at Darrell Charles Court Sheltered Housing Scheme, Uxbridge.	Cabinet will consider the Local Plan - Part 2: Draft Development Management Policies, Sites Allocation and Designations and the Policies Map following the outcome of a further round of consultation, before the Local Plan is submitted to the Secretary of State for examination.
Decision	Cabinet meeting - 18 .	Budget 2014/15 Outturn	Quarterly Planning Obligations Monitoring report	inet meeting	Darrell Charles Cour - Roof Refurbishmen & Solar Panels	Local Plan - Part 2
Ref	Cab	36	S	Cab	37	38

## Agenda Item 8

# Work Programme and Review Topics for the Next Municipal Year

#### Contact officer: Ainsley Gilbert Telephone: 01895 250692 Email: agilbert@hillingdon.gov.uk

#### **REASON FOR ITEM**

This report is to enable the Committee to review meeting dates and forward plans. This is a standard item at the end of each agenda.

#### **MEETINGS**

25 Jun 2015	Major Review 1 – agree potential review topic for first major review	
	Work Programme – review the annual work programme	
Venue: CR4	Cabinet Forward Plan – review forthcoming decisions	
	Update on implementation of recommendations from past reviews	
29 Jul 2015	Major Review 1 – consideration of scoping report	
	Consideration of Budget Planning Report for Residents Services 2015/16	
Venue: CR5	Work Programme – review the annual work programme	
	Cabinet Forward Plan – review forthcoming decisions	
23 Sep 2015	Major Review 1 – First witness session	
	Work Programme – review the annual work programme	
Venue: CR5	Cabinet Forward Plan – review forthcoming decisions	
15 Oct 2015	Major Review 1 – Second witness session	
	Work Programme – review the annual work programme	
Venue: CR6	Cabinet Forward Plan – review forthcoming decisions	
	1	
12 Nov 2015	Major Review 1 – Third witness session	

12 100 2013		
	Review 2 – agree potential review topic for single meeting review	
Venue:	Work Programme – review the annual work programme	
CR3a	Cabinet Forward Plan – review forthcoming decisions	

19 Jan 2016	Review 1 - consideration of draft final report	
	Review 2 - consideration of scoping report	
Venue: CR5	Annual Safety at Sports Grounds Report	
	Budget Report for consideration	
	Work Programme – review the annual work programme	
	Cabinet Forward Plan – review forthcoming decisions	

24 Feb 2016	Review 2 - witness session	
	Work Programme – review the annual work programme	
Venue: CR4+4a	Cabinet Forward Plan – review forthcoming decisions	

23 Mar 2016	Review 2 - consideration of draft final report	
	Update on the Council's and other bodies' responses to flooding in the	
Venue: CR5	Borough	
	Work Programme – review the annual work programme	
	Cabinet Forward Plan – review forthcoming decisions	

27 Apr 2016	Consideration of topics for major reviews for the next Municipal Year	
	Update on implementation of recommendations from past reviews	
Venue: TBC	Work Programme – review the annual work programme	
	Cabinet Forward Plan – review forthcoming decisions	

#### **FUTURE REVIEW TOPICS**

At the last meeting the committee suggested shops selling legal highs, fly tipping, and the protection of war memorials. Members are welcome to suggest any further topics they have either for a review or an information update, in order that exploratory work can be undertaken before the first meeting of the new municipal year, when the work programme will be confirmed.

#### **OPTIONS OPEN TO THE COMMITTEE**

- 1. To note dates for meetings
- 2. To make suggestions for future working practices, reviews, and updates.