


BEFORE



Area as it was before improvements






Area as it was before improvements





Area as it was before improvements



Area as it was before improvements

AFTER



Area after site clearance



Footpath installation



New fencing installed



New fencing installed



Finished footpath with wild flower mix (Poppy and Golden Coreopsis)



Finished footpath with wild flower mix (Poppy and Golden Coreopsis)